PLL Error – AR8200

Information found in the web

One nasty problem I had on my original 8200 was that the battery saver feature was able to unlock the PLL (a piece of radio circuitry which assures that the radio remains tuned to the requested frequency) which effectively negates the radio's ability to receive a signal

On my 8200 all I had to do was turn on the power saver, wait for it to go into power saver mode, then turn the squelch fully open or hold down the Monitor key. Instead of opening the squelch and getting a rush of static like you'd expect, the radio would, instead, respond by display "PLL Error". To remove this error, I had to tune to another frequency